

A4P8, PQ Mt Mark

Project	2018 CSI GPS
Created	2018-01-09 15:51:35 NZDT by Neville Palmer
Updated	2018-04-12 10:55:19 NZST by Neville Palmer
Location	-43.95103302, 169.0696906
Status	■ Excluded
Deployment Status Comment	Mark destroyed. 2m Nelson Beacon has been cut down and iron tube is bent over. Concrete block which contains iron tube is loosely sitting on surface amongst rubble.
Geodetic Code	A4P8
Station Name	PQ Mt Mark
Station Height (m)	1501.4466
Station Height (ft)	4926

Mark, Site & Photo Details

Mark & Protection Details

Mark Type	Iron Tube
Mark Physical State	Damaged
Mark Description	This mark is used for deformation monitoring, do not alter the ground mark in any way. 1" tube and is on a lean. It appears to have been fixed into this position.
Additional mark or site notes (GNS use only)	There are some nearby (car sized) boulders which may be useful for reestablishing a new site. Summit is composed of loose boulder sized rubble, not suitable for a new mark.

Plates & Plaques

ID Plaque (bronze)	ID Plaque does Not Exist and was Not Installed
ID Plate (aluminium)	ID Plate does Not Exist and was Not Installed
Information Plate (aluminium)	Info Plate does Not Exist and was Not Installed

Protection

Primary Protection	No Protection
Secondary Protection	No Protection

Beacon Details

Beacon Type	2m Metal Beacon, Clarke, Nelson, Gisborne
Additional Beacon Notes (GNS use only)	Beacon is lying on its side next to mark. Badly damaged by either lightning strike and/or high winds.

Maintenance Completed and Required

Mark Maintenance Completed	No
Beacon Maintenance Completed	No
Protection Maintenance Completed	No
Mark Maintenance Required	No
Beacon Maintenance Required	No
Protection Maintenance Required	No

Verification

Have all mark and protection fields above been updated or verified to be correct?	Yes
---	-----

Site & Access Details

Access and Location Description	Helicopter. Good landing place on flat ledge approximately 20 m to the south-east of summit of Mt. Marks. Helicopter can easily get both skids down.
Access vehicle	Heli
GNSS Suitability	Good

Cell Phone Network Coverage

Spark	No signal or unreliable signal
Vodafone	No signal or unreliable signal
2 Degrees	No signal or unreliable signal

Verification

Have all site & access fields above been updated or verified to be correct?	Yes
---	-----

Photographs

Photo of Survey Mark



Photo of Immediate Site



Photo of Extended Site



Verification

Is there at least one photo taken for each field above?	Yes
Have any mark, site or photo details been updated or verified?	No - I have no intention of updating or verifying this info.

Owner & Contact Details

Owner & Contact

Contact Details from the LINZ GDB

Owner/Contact	DoC - West Coast Tai Poutini Conservancy
---------------	--

Phone	03 751 0807
Address	Main Road, PO Box 9, Fox Glacier,

Owner

Is the owner known?	Yes
Last Name	South Westland - Weheka Area Office
Address	Main Road, PO Box 9, Fox Glacier,
Phone	03 751 0807

Site Contact

Is the site contact person known?	Same as owner
-----------------------------------	---------------

Access Contact

Is the access contact person known?	Same as site contact
-------------------------------------	----------------------

Verification

Have all owner & contact fields above been updated or verified to be correct?	Yes
Have any owner or contact details been updated or verified?	No - I have no intention of updating or verifying this info.